

Spare part list

DIA 400 W diamond core drill

DUSS

Description	Order-No.	Quantity	Description	Order-No.	Quantity
Motor housing	DIA400W-1	1	Gear 3	DIA400W-99	1
Gear cover	DIA400W-2	1	Sliding gear wheel	DIA400W-100	1
Bearing seat	DIA400W-3	1	Spindle gear	DIA400W-101	1
Cover connection box	DIA400W-4	1	Support washer	DIA400W-103	1
Armature, 230V	DIA400W-5	1	Break disk A	DIA400W-104	2
Field, 230V	DIA400W-6	1	Disc	DIA400W-105	3
Card	DIA400W-7	1	Protective cover	DIA400W-106	2
Frigistor	DIA400W-8	1	Break disk B	DIA400W-107	2
Switch seal	DIA400W-11	1	Ring	DIA400W-109	1
Field pin insulating hull	DIA400W-12	2	Nipple	DIA400W-110	1
Brush holder	DIA400W-13	1	Conveying screw	DIA400W-112	1
Air line disc	DIA400W-14	1	Roller bearing	DIA400W-115	1
Connection box sealing	DIA400W-15	1	Ball bearing	DIA400W-120	1
Connection box	DIA400W-16	1	Ball bearing	DIA400W-121	1
Carbon brush	DIA400W-17	2	Roller bearing	DIA400W-122	1
Carrier handle	DIA400W-19	1	Needle bush	DIA400W-123	2
Ball bearing	DIA400W-20	1	Needle bush	DIA400W-124	1
Ball bearing	DIA400W-21	1	Axial ball bearing	DIA400W-125	1
Ball bearing balancing disc	DIA400W-22	1	Needle thrust bearing	DIA400W-126	1
O-ring seal 32x3	DIA400W-23	1	Washer	DIA400W-127	1
Sealing ring	DIA400W-25	1	O-ring seal 102x3	DIA400W-128	1
Cheese head screw M6x35	DIA400W-26	4	O-ring seal 20x3	DIA400W-129	1
Cheese head screw M5x120	DIA400W-27	2	O-ring seal 11x2,5	DIA400W-130	1
Lens head screw M4x40	DIA400W-28	4	Sealing ring	DIA400W-131	1
Lens head screw M4x6	DIA400W-29	2	Sealing ring	DIA400W-132	1
Countersunk head screw 4x6	DIA400W-30	2	Sealing ring	DIA400W-133	1
Flat headed screw 4x6	DIA400W-31	1	Hose	DIA400W-134	1
Lens head screw 3,9x9,5	DIA400W-32	1	Ball valve and lever	DIA400W-135	1
Hexagon nut M5	DIA400W-33	2	Nipple	DIA400W-136	1
Grooved pin	DIA400W-34	4	Sealing ring	DIA400W-137	3
Lens head screw M4x6	DIA400W-35	1	Disk spring	DIA400W-140	3
Lock washer M6	DIA400W-36	7	Spring	DIA400W-141	1
Spring washer	DIA400W-37	2	Ball dia. 5mm	DIA400W-142	1
Spring washer	DIA400W-38	1	Ball dia. 4mm	DIA400W-143	2
Washer M4	DIA400W-39	3	Feather key 6x45	DIA400W-144	1
Headless screw	DIA400W-40	1	Feather key 4x10	DIA400W-146	1
Capacitor	DIA400W-48	1	Index bolt 6x10	DIA400W-147	1
Cord screwing	DIA400W-54	1	Index bolt 5x15	DIA400W-148	1
Switch	DIA400W-56	1	Index bolt 3x16	DIA400W-149	1
Cord, plug and PRCD	DIA400W-75	1	Washer	DIA400W-150	1
DIA400W nameplate	DIA400W-85	1	Retaining ring	DIA400W-151	1
Gear housing	DIA400W-90	1	Circlip	DIA400W-152	1
Water connection	DIA400W-91	1	Hexagon nut M22x1,5	DIA400W-160	1
Gear handle	DIA400W-92	1	Cheese head screw M6x50	DIA400W-161	3
Gearshift	DIA400W-93	1	Cheese head screw M5x12	DIA400W-162	1
Tool bit driver	DIA400W-94	1	Cheese head screw M5x45	DIA400W-163	3
Shaft	DIA400W-95	1	Lock washer M5	DIA400W-165	1
Shaft	DIA400W-96	1	Quick release ring	DIA400W-175	1
Layshaft gear	DIA400W-97	1	O-ring seal 32x1,5	DIA400W-176	1
Gear 1	DIA400W-98	1			

DUSS

DIA 400 W

